

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE															
LEG FABRIC ATTACHMENT RING ITEM 104 (1) LEFT (1) RIGHT ----- 10155-03 (2)	2/1R	104FM28T  Loss of primary adjustable bracket pin.  Defective material; bracket, adjustable pin, retention screws.	END ITEM: Loss of primary axial load restraining capability.  GFE INTERFACE: Axial load will be transferred to secondary restraint.  MISSION: None.  CREW/VEHICLE: None with single failure. Loss of crewman with loss of secondary restraint.  TIME TO EFFECT /ACTIONS: Minutes.  TIME AVAILABLE: N/A  TIME REQUIRED: N/A  REDUNDANCY SCREENS: A-PASS B-N/A C-PASS	A. Design - The adjustable primary bracket is fabricated from 17-4 stainless steel. The brackets are machined, ultrasonic cleaned, passivated and either electropolished or dry hone finished. The primary adjustable link is fabricated from 17-4 stainless steel and has a 16 finish to preclude primary webbing abrasion. The adjustable link is retained by a stainless steel pin that is held in place by a single screw.  Tensile testing of the restraint bracket pin demonstrated a minimum ultimate strength of 1655 lbs and a yield strength of 1493 lbs. At 4.4 psid (normal operating pressure) the S/AD limit load is 574 lbs, giving the bracket pin a safety factor of 2.9 for ultimate and 2.6 for yield. At 5.5 psid (max failure pressure) and 8.8 psid (max BTA operating pressure) the bracket pin provides safety factors for ultimate of 4.5 and 5.8 respectively. The S/AD minimum safety factor for hardware at 4.4 psid is 2.0 for ultimate and 1.5 for yield. At both 5.5 psid and 8.8 psid the S/AD minimum safety factor for hardware is 1.5 for ultimate.  B. Test - Acceptance: See inspection.  PDA: During PDA, the following inspection points are performed at the LTA assembly level in accordance with ILC Document 0111-710112. Inspection for cleanliness to VC level. Verification of proper engagement and operation.  Certification: The fabric attachment ring was successfully tested (manned) during SSA certification to duplicate 458 hours operational life (Ref. ILC Report 0111-711330). The following usage, reflecting requirements of significance to the ring, was documented during certification:  <table border="1"> <thead> <tr> <th>Requirement</th> <th>S/AD</th> <th>Actual</th> </tr> </thead> <tbody> <tr> <td>Knee/Cycles</td> <td>9078</td> <td>20000</td> </tr> <tr> <td>Don/Doff</td> <td>98</td> <td>400</td> </tr> <tr> <td>Pressure Hours</td> <td>458</td> <td>916</td> </tr> <tr> <td>Walking Steps</td> <td>4320</td> <td>77760</td> </tr> </tbody> </table> C. Inspection - Components and material manufactured to ILC requirements at an approved supplier are documented from procurement through shipping by the supplier. ILC incoming receiving inspection verifies that the materials received are as identified in the procurement documents, that no damage has occurred during shipment and that supplier certifications have been received which provides traceability information.  The following MIPs are performed during the brief assembly manufacturing process to assure that the failure causes are precluded from the fabricated item: 1. Visual inspection upon completion of the restraint webbing pull test for signs of damage.	Requirement	S/AD	Actual	Knee/Cycles	9078	20000	Don/Doff	98	400	Pressure Hours	458	916	Walking Steps	4320	77760
Requirement	S/AD	Actual																	
Knee/Cycles	9078	20000																	
Don/Doff	98	400																	
Pressure Hours	458	916																	
Walking Steps	4320	77760																	

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		104FM28T		<p>During PDA, the following inspection points are performed at the arm assembly level per ILC Document 0111-710112:</p> <ol style="list-style-type: none"><li>1. Inspection for cleanliness to VC level.</li><li>2. Visual inspection for damage, wear or material degradation.</li><li>3. Visual inspection for damage following proof-pressure test.</li></ol> <p>D. Failure History - None.</p> <p>E. Ground Turnaround - Inspected for non-EET processing pre FEMU-R-001, Pre-Flight visual inspection. None for EET processing. Additionally, every 4 years chronological time or 229 hours of manned pressurized time, the fabric attachment ring is disassembled, cleaned, inspected, lubricated and reassembled.</p> <p>F. Operational Use - Crew Response - PreEVA/PostEVA: If not detected, no response. If detected audibly or tactilly, troubleshoot problem. If no success use spare EMU available. EVA: Single failure not detectable, no response.</p> <p>Training - No training specifically covers this failure mode.</p> <p>Operational Consideration - Not applicable.</p>

EXTRAVEHICULAR MOBILITY UNIT  
SYSTEMS SAFETY REVIEW PANEL REVIEW  
FOR THE  
I-104 LOWER TORSO ASSEMBLY (LTA)  
CRITICAL ITEM LIST (CIL)

EMU CONTRACT NO. NAS 9-97150

Prepared by: *J. Amman*  
HS - Project Engineering

*M. Snyder*  
HS - Reliability

*R. Mumford 4/24/02*  
HS - Engineering Manager

Approved by: *[Signature]* 2/24/02  
~~NASA - SSA/SSM~~

*[Signature]* 5/24/02  
~~NASA - SSA/SSM~~

*Charles J. Sager* 5.29.02  
~~NASA - SSA/SSM~~

*Paul S. Burke* 5-30-02  
~~NASA - MOD~~

*Joe Tamm* 6/04/02  
~~NASA - SSA/SSM~~

*[Signature]* 6/3/02  
NASA - Program Manager